



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

February 06, 2013

Reviewed: 

Mine Name: Browns Canyon Rock Quarry	Permit Number: M/043/0017
Operator Name: Castle Valley Stone, LLC.	Inspection Date: October 19, 2011
Inspector(s): L Hepler and W. Western	Time: 9:00 AM
Other Participants: Operators Representative	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 04-18-2011 **Bond Amount:** \$83,100 **Permit fee** is up to date for 2012, 2013 fees are being processed

Purpose of Inspection: Routine annual Inspection. This site was inspected as a large mine site on 09-08-2010.

Inspection Summary: At the time of the inspection, Castle Valley Stone had transferred the permit. Footprint at the time of inspection appeared to have expanded further to the west into the ridgeline and the scrub oak. There is a landslide/debris flow that has enlarged the foot print to the north.

Photos were taken to document site conditions.

Conclusions and Recommendations: Permit NOI needs to be updated based on current disturbance on the ground and the Operators plan. Bond should be increased to account for the larger footprint. Weeds need to be controlled, as shown in attached photos. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature 

LAH:eb

cc: Castle Valley Stone LLC – Jeff Sagers

O:\M043-Summit\M0430017-BrownsCynRock-RockProducts\inspections\Insp-10192011.doc





Scales



Overview of the site – note debris flow



Gate



Landslide scarp in the pit



Highwall looking west



Highwall from the top looking east – note weeds



Overview – note west edge of pit



Product on pallets